

SECRET

IB - 317/63
 15 November 1963
 Copy 1 of 8

MEMORANDUM FOR: Chief, Manufacturing and Services Division, ORR

ATTENTION : 25X1

THROUGH : Chief, Requirements Branch, Reconnaissance Group, CGS

FROM : Chief, CIA/PID (NPIC)

SUBJECT : Analysis of Repair of Hurricane Damage to Certain Areas in Cuba

REFERENCE : (1) ORR Requirement No. C-RR3-80,773
 (2) CIA/PID Project No. C 1605/63

1. This memorandum is in response to the above referenced requirement concerning the state of repair of selected sections of the Cuban transportation systems that were previously reported to be damaged by Hurricane Flora in Memorandum No. GMB 691/63 in answer to ORR Requirements Nos. C-RR3-80,721 and C-RR3-80,726.

2. The selected sections were as follows:

AREA NO.	COORDINATES	DESCRIPTION	
1	20 36 30N/76 57 30W	RR bridge is in and appears to be operational. 	25X1
2	20 35 45N/76 55 40W	Repair equipment on the scene, no repairs visible as of 	25X1
3	20 32 50N/76 55 40W	RR bridge is operational and supporting rail traffic as of 	25X1
4	20 52 35N/76 49 30W 20 49 30N/76 43 50W	Only washout, approximately $\frac{1}{2}$ mile NW of Omala, still exists- repair equipment is on the scene as of 	25X1
5	20 47 30N/75 48 30W	RR bridge is not usable. Approximately half of it is in place. Scale and obliquity preclude further analysis. 	25X1

DDR-DUPE

SECRET

SECRET

Page 2

<u>AREA NO.</u>	<u>COORDINATES</u>	<u>DESCRIPTION</u>
6	20 38 20N/75 56 20W	RR bridge has train crossing it. Highway bridge is complete and supporting truck traffic. [redacted] 25X1
7	20 45 00N/76 29 30W to 20 33 30N/76 30 00W	All washouts have been repaired and are supporting rail traffic as of [redacted] 25X1
8	20 33 30N/76 0300W	RR bridge appears to be in complete repair as of [redacted] 25X1
9	21 11 20N/76 37 00W	Bridges out, no repair equipment visible - [redacted] 25X1
10	21 07 50N/76 12 30W	Alternate highway bridge built next to washed out bridge. Truck traffic was observed on new bridge. [redacted] 25X1
11	21 09 30N/76 33 45W	Highway bridge is still damaged (approaches washed away)
12	21 09 30N/76 18 30W 21 10 00N/76 24 30W	Road appears to be in complete repair and supporting truck traffic. RR washouts also appear to be in operational condition though no traffic was observed. [redacted] 25X1
13	20 23 00N/76 39 20W	RR bridge repairs appear to be complete. Road bridge still has structural damage to east approach. [redacted] 25X1
3.	Photography used in this requirement was:	25X1
	Photo Mission [redacted]	
	Photo Mission [redacted]	
	Photo Mission [redacted]	
4.	The photo analyst on this project was [redacted] who can be contacted on extension 2547 should you have any questions concerning this project. This requirement is considered complete. [redacted] 25X1	

SECRET